

HISTORIC AMERICAN BUILDINGS SURVEY
INDEX TO PHOTOGRAPHS

HABS
116,
16-CHIG,
109-

Granada Theater
6427-41 North Sheridan Road
Cook County
Chicago, Illinois

HABS No. IL-1156

Documentation: 7 Exterior Photographs (1989)
 22 Interior Photographs (1989)
 2 Photographic Copies of Historic Photographs (c.1933)
 12 Data Pages (1989)

Thomas C. Yanul, Photographer, September & October 1989

- IL-1156-1 VIEW OF BLOCK FROM SOUTHWEST LOOKING NORTHWEST.
- IL-1156-2 VIEW OF BLOCK FROM NORTHWEST LOOKING SOUTHEAST.
- IL-1156-3 LOOKING EAST, VIEW OF COMMERCIAL OFFICE SECTION, NORTH
 PORTION OF THEATER COMPLEX.
- IL-1156-4 LOOKING EAST, VIEW OF THEATER ENTRANCE, FRONT.
- IL-1156-5 LOOKING EAST, SOUTHEAST, VIEW OF THEATER FRONT.
- IL-1156-6 DETAILS OF TOP PORTION OF THEATER FRONT, LOOKING EAST.
- IL-1156-7 DECORATIVE DETAIL OF THEATER FRONT ABOVE MARQUE, SOUTH SIDE
 OF MAIN WINDOW.
- IL-1156-8 LOOKING SOUTH, GROUND FLOOR, INNER LOBBY, AREA IMMEDIATELY
 WEST OF THE OPEN MULTI-STORY LOBBY.
- IL-1156-9 GROUND FLOOR, LOOKING EAST, VIEW ALONG THEATER SPACE ENTRY
 DOORS.
- IL-1156-10 FROM GROUND FLOOR, LOOKING EAST INTO MAIN LOBBY SPACE.
- IL-1156-11 FROM WEST END 2ND FLOOR LOBBY, LOOKING EAST.
- IL-1156-12 FROM WEST END 2ND FLOOR LOBBY, LOOKING EAST.
- IL-1156-13 SECOND FLOOR LOBBY, LOOKING EAST, NORTHEAST, THEATER ENTRY
 DOORS TO BALCONY ALONG COLUMNED CORRIDOR.
- IL-1156-14 MAIN LOBBY CEILING FROM GROUND LEVEL (AXIS IS EAST-WEST).
- IL-1156-15 INSIDE THEATER PROPER. GROUND FLOOR, UNDER BALCONY, AT REAR
 OF SEATING AREA (SOUTH END) LOOKING EAST. VIEW OF
 DECORATIVE CEILING COVE.
- IL-1156-16 GENERAL VIEW OF GROUND LEVEL SEATING AREA, UNDER BALCONY,
 LOOKING EAST.

- IL-1156-17 GENERAL VIEW, GROUND LEVEL AT BALCONY PERIMETER. SHOWS
ORCAN ALCOVE. LOOKING EAST, NORTHEAST.
- IL-1156-18 FROM STAGE, LOOKING SOUTHWEST SHOWING ALCOVE AND STAIRCASE
ENTRY.
- IL-1156-19 HORIZONTAL VIEW FROM STAGE LOOKING SOUTH.
- IL-1156-20 VIEW OF CEILING FROM STAGE.
- IL-1156-21 SECOND FLOOR LOBBY, WEST END. VIEW OF FIREPLACE, LOOKING
SOUTH. THEATER FROM WINDOWS TO RIGHT.
- IL-1156-22 CEILING IN 2ND FLOOR LOBBY, WEST END AREA. CEILING AXIS IS
NORTH-SOUTH.
- IL-1156-23 DETAIL, 2ND FLOOR LOBBY, WEST END, STAIRCASE AT NORTH WALL.
- IL-1156-24 2ND FLOOR WALKWAY, EAST-WEST AXIS. THEATER PROPER TO LEFT.
- IL-1156-25 DETAIL, ALCOVE 2ND FLOOR LOBBY WALKWAY. LOOKING NORTH.
- IL-1156-26 2ND FLOOR, MAIN LOBBY AREA. TYPICAL PAIRED COLUMNS. VIEW,
LOOKING SOUTH.
- IL-1156-27 SECTION OF MAIN LOBBY CEILING.
- IL-1156-28 2ND FLOOR, WEST END, LOOKING SOUTH AT FIREPLACE IN OUTER
LOBBY AREA.
- IL-1156-29 2ND FLOOR, WEST END, LOOKING NORTH AT DETAIL OVER DOORWAY
ENTRANCE TO STAIRCASE.
- IL-1156-30 LOOKING EAST, NORTHEAST, VIEW OF THEATER FRONT WITH ORIGINAL
MARQUE (HISTORIC PHOTOGRAPH, C. 1933).
- IL-1156-31 INSIDE THEATER PROPER. FROM WEST END OF BALCONY, LOOKING
EAST, NORTHEAST (HISTORIC PHOTOGRAPH, C. 1933).